

MONUMENT RECORD


Corner I.D. #

Q-3

STATE OF INDIANA - COUNTY OF MONROE

Section Two (2), Township 10 North, Range 1 West

Monument Description & Remarks: Found Sandstone at West 1/4 corner of section. Stone was 0.4' x 0.6' x 0.7' out of ground, with chisled "X" on top. Stone was found loose in ground, but firmed up by County Surveyor.



State of Indiana
County of Monroe

Space
Reserved For
Recording
Officer

I, Michael W. Friley, County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 26th day of April, 1996 A.D.

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office
United States Government Agency

Monroe County Surveyor
Title

Field Book:

96-01

Page:

46

MONUMENT RECORD


Corner I.D. #

Q-3

STATE OF INDIANA - COUNTY OF MONROE

Section Two (2), Township 10 North, Range 1 West

Monument Description & Remarks: Stone found at West 1/2 mile (West 1/4
1/4 Corner). Witnessed by Tom Martin, Asst. State Surveyor, 9/11/84.



State of Indiana
County of Monroe

Space
Reserved For
Recording
Officer

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 2nd day of November, 19 93 A.D.

Indiana Registered Land Surveyor No. _____ or

Morgan-Monroe State Forest
United States Government Agency

Darrell Breedlove, Timber Specialist
Title

Field Book:

n/a

Page:

n/a

SECTION 2, T 10 N, R 1 W

On May 1, 1984, boundary line work was done as follows:

-a stone was found at the mid-section point of the west section line (it was not witnessed).

-old fence wire was found along the east side of $W\frac{1}{2}$, $NW\frac{1}{4}$ that leads to a prominent corner post at the NE corner $NW\frac{1}{4}$, $NW\frac{1}{4}$.

-a Public Hunting Area sign was found at NE corner $NW\frac{1}{4}$, $NW\frac{1}{4}$ and an old state forest boundary sign was found in the first drainage south of the $\frac{1}{4}$, $\frac{1}{4}$ corner.

-compass reference lines were ran east (1° W declination) from the stone and south from the corner post. The south running line was extended to the south edge of the section. No markers were located that showed where the SE corner of $W\frac{1}{2}$, $NW\frac{1}{4}$ should be established.

-a boundary survey request was filed since the SE corner of $W\frac{1}{2}$, $NW\frac{1}{4}$ is in dispute.

Darrell Breedlove, Timber Specialist

2. On Sept. 11, 1984, the following was done by Breedlove and Martin
- a stone at SE corner of $W\frac{1}{2}$, $NW\frac{1}{4}$ was set as directed by the state surveyor, Bob Vollmer. It was witnessed as described by Martin on the next page. A steel fence post was driven next to the stone. (See 5a.)
 - a steel fence post was driven on the line approx. 350 ft. west of the before mentioned stone as directed by the state surveyor.
 - a stone at SE corner of $W\frac{1}{2}$, $SW\frac{1}{4}$ was witnessed as described by Martin, and a steel fence post was driven next to it. Vollmer believes it is a good stone. (See 5a.)
 - a stone at mid-section on the W section line was witnessed as described by Martin. (Vollmer believes it is a good stone.)
 - the boundary line was painted on the south and east sides of $W\frac{1}{2}$, $NW\frac{1}{4}$ on the state side and signs were posted at the SE corner and at the mid-point of the east side of $W\frac{1}{2}$, $NW\frac{1}{4}$. Vollmer set a steel fence post at this mid-point in Aug. '84 (a $\frac{1}{4}$, $\frac{1}{4}$ corner). A sign was also posted at the NE corner of $W\frac{1}{2}$, $NW\frac{1}{4}$.

Darrell Breedlove, Timber Specialist

*Did
check
this?*

2.

Section 2



error discovered
3/12/89
D. Breedlove

PK NE SIDE
9" BLACK WALNUT 3" FROM
BASE

PK NE SIDE OF 13"
BLACK WALNUT 3" FROM BASE

1.07
S 62° W
As. 242

11.12
N 47° E
As. 47

PK NW SIDE OF AN 11" BLACK
WALNUT 3" FROM BASE.

STONE SET & STEEL FENCE
POST ON SE SIDE

At the direction of Vollmer, this
stone was moved 12.5 ft. S 3° W
on Oct. 18, 1989 by Breedlove.

(See 5a)

Section 2



error discovered
12/10/89
D. Breedlove

STONE FOUND
Fence Post Set NW SIDE
OF STONE

South 1/4 corner
of the SW 1/4

PK SW SIDE BASE OF 19" BLACK OAK


14.40
N 84° W
As. 274

18.70
S 61° E
As. 119

PK W SIDE BASE OF 21"
Scarlet Oak.

PK E SIDE BASE OF 13" BLACK OAK

Section 2



North 1/4 corner
of Sec. 2

PK SIDE 18" RED OAK

STONE FOUND

PK SIDE 14" RED
OAK

25.31
S 70° W
As. 127

9.29
N 22° E
As. 22

PK SIDE 12" SHAGBARK
HICKORY

Tom Martin
Deer State S.

MONUMENT RECORD

Corner I.D. #

Q-3

STATE OF INDIANA - COUNTY OF MONROE

Section Three (3), Township 10 North, Range 1 West

Monument Description & Remarks: Corner located by State Highway Survey
Location Team. See drawing below for description.

Recovery Tie Drawing

APP E 1/4 Cor SEC 3, T-10N, R-1W
WASHINGTON TWP.
MONROE Co.

Type Monument + Cut in Stone
Depth 0.20' Above
By PARTY #1
Date AUG 2, 1996

State Form 40180

State of Indiana
County of _____

Space
Reserved For
Recording
Officer

I, M.W. L., hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this _____ day of _____, 19____ A.D.

Indiana Registered Land Surveyor No. _____ or

Field Book:

United States Government Agency

Page:

Title